











Presenter M. D. Erminger

Date February 14, 2002 Page 1

STS-109

Flight Readiness Review













M. D. Erminger			
Date	February 14, 2002	Page	2

Approach and General Description

S&MA held reviews in preparation for the STS-109 Flight Readiness Review on 6 and 11 February 2002 and is ready to proceed toward launch countdown.

FRR Briefing Overview

- Significant assessments discuss
- Special topics
 - NASA Safety Reporting System (NSRS) discuss
 - Space Shuttle Hazard Analysis discuss
 - Space Shuttle FMEA/CIL discuss
- Space Shuttle Independent Assessments none
- Significant Open Work none
- o CoFR Exceptions none
- o Open Action Items none













Present	er M. D. Erming	M. D. Erminger		
Date	February 14, 2002	Page	3	

Significant Assessments

Orbiter/GFE

- Raytheon Transistor Intermetallic Growth *Significant Open Work
- STS-108 Drag Chute Problem

SSME

Main Injector LOX Post Tip Indentations

<u>SRB</u>

• APU Controller Module Diode Test Failure

ADDITIONAL ASSESSED ITEMS ARE IN THE BACKUP CHARTS













Presen	M. D. Erminger			
Date	February 14, 2002	Page	4	

Significant Assessments

<u>ET</u>

• ET-118 LO2 Feedline Foam Delamination

Launch & Landing

- STS-108 Handrail Investigation
- STS-108 GH2 Vent Arm Anomaly
- Hazardous Gas Detection System 2000 Status

ADDITIONAL ASSESSED ITEMS ARE IN THE BACKUP CHARTS













Presente	M. D. Erminge	M. D. Erminger		
Date	February 14, 2002	Page	5	

Significant Assessments

Safety Improvements Incorporated on OV-102 During Major Modification

- APU System Fuel & GN2 Servicing QD Upgrade
 - Eliminated hydrazine leak path
- Kapton Wire Inspection
 - Eliminated possible wire shorts
 - 413 segments repaired
- OMS/RCS Crossfeed Line Replacement
 - Eliminated on-orbit thermal constraint
- Aft Avionics Bay Coldplate Replacements
 - Eliminated corrosion & coining
- MPS Helium Check Valve Replacement
 - Eliminated cocking
- Radiator Impact Protection & Isolation
 - Reduced probability of loss of a FCL in the event of a MMOD impact

- 576 Bulkhead Coldplate/Coolant Line Removal
 - Eliminated a critical failure mode
- Replace Display Driver Unit with Device Driver Unit (DDU)
 - Replaced hardware with known failure history
- 20 G Floor Modification (CDR, PLT, and MS3)
 - Restored structural margin of safety
- Wing Strut Tube Modifications
 - Restored structural margin of safety
- Base/Dome Heat Shield Structural Repair
 - Eliminated existing damage
- MEDS Installation
 - Replaced aging/obsolete electromechanical flight instruments













Presenter M. D. Erminger					
	Date Fek	oruary 14, 2002	Page	6	

NSRS Summary

There are no NASA Safety Reporting System reports open that are applicable to STS-109.













M. D. Erminger

Date February 14, 2002 Page 7

Hazard Analysis Summary

There are no new Accepted Risk hazards identified for STS-109.













Presenter	M. D. Erminger			
Date Fel	oruary 14, 2002	Page	8	

FMEA/CIL Summary

There are no new Criticality 1 failure modes identified for STS-109.













Presenter M. D. Erminger

Date February 14, 2002 Page 9

STS-109 Readiness Statement

With the satisfactory completion of identified open work, Safety and Mission Assurance has no constraints to STS-109. S&MA has no issues that constrain any of the mission success criteria.

/S/ John Casper	/S/ Shannon Bartell
SR&QA Director, JSC	Director, KSC Safety, Health and Independent Assessment
/S/ Amanda Goodson	/S/ Bill Higgins
S&MA Director, MSFC	Chief, Shuttle S&MA, KSC
/S/ Mark Erminger	/S/ Hank Davis
SS SR&QA Manager	HEDS IA Director
	/s/ Mike Smiles
	S&MA Manager, SSC













Presenter M. D. Erminger

Date February 14, 2002 Page 10

STS-109

Flight Readiness Review

Backup Package













Presen	ter M. D. Erming	M. D. Erminger			
Date	February 14, 2002	Page	11		

Additional Assessments

Orbiter/GFE

- First Flight/Critical Process Change
 - First Flight of OV-102 Following Major Modification
 - First Flight Of The Device Driver Unit
- STS-108 IMU #2 BITE Failure
- STS-108 Flash Evaporator System Controller Anomaly
- STS-108 RCS Thruster Failures R4U And F3F
- STS-108 Space to Space Orbiter Radio Problems
- Water In The Forward Fuselage
- Hydraulic Main Pump Mounting Flange Washer Issue
- Hydraulic Main Pump Port Cap Bolt Issue
- Payload Pay Door AC1 Phase A Missing













Presente	M. D. Erminge	M. D. Erminger		
Date	February 14, 2002	Page	12	

Additional Assessments

RSRM

- New O-ring Resiliency Test Data
- Nozzle Bondline Residual Stress Waiver

<u>ET</u>

- First Flight/Critical Process Change
 - New Ice/Frost Foam Mold and LH2 PAL Ramp Angle
 - LH2 Burst Disc Repair
 - LO2/LH2 Ullage Pressure Flex-hose Process Change
 - LO2 Tank Dome Cap Reallocation

SRB

- SRB/ET Attach Ring/Attach Strut Closeout Cover Debond
- SRB TVC Hydraulic Pump Bolt Torque Preload

<u>SSME</u>

LPOTP Nozzle Vane Cracks

KSC SHIA

- Effectiveness of Mission Processing Team and Contractor Control Working Group
- Effectiveness of Launch Processing Team